

EQ# 63214294

Certificate of Inspection

HUSKY OIL OPERATIONS LTD
BOX 6525 STN D
CALGARY/WESTERN CDA UPSTREAM
ATTN: RON CHAPMAN
CALGARY, AB
T2P 3G7

PREFERRED RE-INSP. INTERVAL: Yr.

YEAR BUILT: 2005

CRN: T3040.2

SERIAL #: 010289-210

VOLUME: 0.215 M3

HEATING SURFACE: 19.5 M2

SURFACE AREA:

COMPANY CODE:

DESCRIPTION: INDIRECT FIRED HEATER COILS

LOCATION: STRACHAN GAS PLT 100/12-32-046-16W5/00

MANUFACTURER: NUSCO SUPPLY & MANUFACTURING INC

FH-RR

Safety Valves

PART	MAX. AUTHORIZED WORKING PRESSURE	MAX. TEMP	MIN. TEMP	VALVE ID	SETTING	CAPACITY	LOCATION
COIL 1	34689 KPA	93 C	-46 C	SV1			TO BE INSTALLED
COIL 2	13962 KPA	93 C	-46 C	SV2			TO BE INSTALLED

OWNER INSTRUCTIONS/REMARKS:

NOT SUBJECT TO ANNUAL FEES AS PER INFORMATION BULLETIN IB03-003 (h)
DIRECT OR INDIRECT FIRED OIL AND GAS PROCESS HEATERS OF THE COIL TYPE;

Owner to verify integrity of vessel by periodic inspection program.

Verify that vessel/boiler is protected by an acceptable ASME Code pressure relief device, of adequate capacity, set at no more than maximum pressure authorized and installed in accordance with the Safety Codes Act & Regulations.

Vessel/Boiler to be installed in accordance with the Safety Codes Act and Regulations.

Safety Codes Officer: BILLEY, HENRY

Signature: 

NOTE: REQUIREMENTS OF THE SAFETY CODES ACT AND THE REGULATIONS ISSUED THEREUNDER:

The owner or person in charge shall report all accidents involving a boiler, pressure vessel or pressure piping system to the district Safety Codes Officer immediately and shall send a full report in writing to the Administrator as required by the Act. No repairs or alterations may be made unless authorized by a Safety Codes Officer.